

Autohaus of McAllen

Certified Inspection



Pre-Owned Vehicle Inspection Checklist

Inspection Date: 20th July 2015	VIN Number: WP0AB29827U782808
Stock Number:	R.O. Number: 2017
Year: 03/2007	Odometer: 27257
Make: PORSCHE	Dealership/Name: Ricardo Lopez
Model: Cayman S	Comments: Vehicle in good condition see report
Technician Performing Inspection: L. Escalona	

Investigate Vehicle	Yes	No
Is this vehicle still covered by its original factory warranty?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Is the Owner's Manual/Warranty Booklet Present?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Are there any open recalls for this vehicle?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Is this vehicle free of any aftermarket modifications like body/chassis lift kits, or engine performance chips?	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Do all vehicle VIN plates match? (engine compartment, door jambs, and dash)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Are there any noticeable signs of Collision Damage?	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Maintenance Inspection	Excellent Condition	Recommend Repair	Repair Required
Engine Oil and Filter	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Air/Cabin Filter	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Hoses/Clamps	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive/Serpentine Belt	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery Status, <u>12.7</u> Volts, Clean and Secure Battery Connections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Battery Tray, Retainer & Vent Tubes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering System & Fluid Levels	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine Coolant Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Brake Fluid level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Differential Fluid Level & Color <u>Amber</u> <u>Clear</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Alternator Charging 14.2 V With full load	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Water Pump (noises, leaks, etc.)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Distributor (Cap & Rotor Condition, Shaft Looseness)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Ignition System Operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Fuel System Operation and Fuel Tank Cap	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Radiator	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant Recovery Tank	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cooling Fan Operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
A/C Condenser & A/C Compressor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Engine/Transmission Mount Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>